

# **LEAKING ACETYLENE BOTTLE** **CAUSES VAN EXPLOSION**

On October 22nd 2010, disaster struck when a massive explosion destroyed a Tradesman's Van.

Emergency Crews were called to the Scene of mayhem at Dunscombe Place in Chelsea Heights Victoria.

Debris was scattered more than 100 metres away (as well as in trees and on house roofs) from the explosion with nearby properties windows being blown out.

As you can see from the image, the Autosafe Cargo Barrier is largely intact whilst the van is severely damaged.

An extract below from a satisfied client.

"I most certainly would not consider installing any other barrier in my future vehicles, and recommend Autosafe Industries products to everyone"



***Insist on Autosafe Products,  
the name says it all.***

4-6 Isa Way Boronia VIC 3155  
P.O Box 183 The Basin 3154  
Phone: +61 3 9720 5533  
Fax: + 61 3 9720 1300  
Email: [sales@autosafe.com.au](mailto:sales@autosafe.com.au)  
Web: [www.autosafe.com.au](http://www.autosafe.com.au)



**AUTOSAFE®**  
I N D U S T R I E S